



# **CLAY FIRE**

18355 Auten Road • South Bend, IN 46637 Telephone: (574) 272-2144  
Fax: (574) 272-4043

## ***For Immediate Release***

---

Date: 05/16/2014

---

Subject: Structure Fire

---

Contact Person: BC Chris Schmitt

---

Today at approximately 1750 Clay Fire Territory was dispatched for a grease fire in the kitchen of a residence in the 51000 block of Columbine Dr. Crews arrived within minutes to find smoke coming from the residence. Crews entered the residence and quickly extinguished the fire, limiting the fire damage to the range and cabinets. There was smoke damage throughout the residence.

The occupants were alerted by the smoke alarm and were able to exit safely. There were no injuries reported. This fire was caused by an unattended fryer.